


Exploded View & Miscellaneous Parts



CAUTION

The mic element must be desoldered and removed from the PCB on order to re-install its protective rubber cover.

Therefore, be careful not to remove this cover unless mic element replacement is necessary.

